

Inspection Photos
Location Name: Anderson MB 33-8J
Location ID: 321306



Photo 1 Wellhead.

Photo 2 Wellhead sign.

Inspection Photos
Location Name: Anderson MB 33-8J
Location ID: 321306



Photo 3 Separator area.

Photo 4 Horizontal Heated Separator.

Inspection Photos
Location Name: Anderson MB 33-8J
Location ID: 321306



Photo 5 Gas Meter Run.



Photo 6 Pig launchers.

Inspection Photos
Location Name: Anderson MB 33-8J
Location ID: 321306



Photo 7 Tank battery.

Photo 8 Tank Battery signs.