

Inspection Photos

November 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325427

Inspection Document #: 714001485

La Plata County, CO

Township: NESW 7 34N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Neleigh 01-07 1
Location ID: 325427

11/12/24
83° E



Photo 1. View of well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Neleigh 01-07 1
Location ID: 325427

11/12/24
137° SE



Photo 2. Southern interim reclamation area composed of Smooth Brome and Western Wheatgrass.

Inspection Photos
Location Name: Neleigh 01-07 1
Location ID: 325427

11/12/24
25° NE



Photo 3. Stormwater BMPs have been installed in the northern portion of the location.

Inspection Photos
Location Name: Neleigh 01-07 1
Location ID: 325427



Photo 4. Wood palette debris/trash has been removed from the active pad.

Inspection Photos
Location Name: Neleigh 01-07 1
Location ID: 325427



11/12/24
9° N

Photo 5. Severe rutting observed at access point. Additional stabilization/grading needed to minimize degradation to access point.