

Inspection Photos

November 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306769

Inspection Document #: 714001486

La Plata County, CO

Township: SWSE 7 34N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Neleigh 01-07 2
Location ID: 306769



Photo 1. View of well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Neleigh 01-07 2
Location ID: 306769

11/12/24
265° W



Inspection Photos
Location Name: Neleigh 01-07 2
Location ID: 306769



Photo 3. Stormwater BMPs installed along the access road have filled with sediment and are no longer functioning, maintenance is needed. Sediment has started to migrate and settle on the access road.