

Inspection Photos

November 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326071

Inspection Document #: 714001487

La Plata County, CO

Township: SENW 8 34N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Gearhart C 1
Location ID: 326071



Photo 1. View of well disturbance taken from the access point facing center.
Note: Weedy debris dominating active pad and interim reclamation areas.



API #: 067-07425

Inspection Photos
Location Name: Gearhart C 1
Location ID: 326071



Photo 2. Erosion issues on location remain persistent. Stormwater BMPs have not been installed correctly, stormwater continues to flow under installed wattles.

Inspection Photos
Location Name: Gearhart C 1
Location ID: 326071



Photo 3. Additional view of weedy kochia debris observed along the northern edge of the disturbance.

Inspection Photos
Location Name: Gearhart C 1
Location ID: 326071



Photo 4. Impacted surface material observed at well head.