

# Inspection Photos

November 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306765

Inspection Document #: 714001489

La Plata County, CO

Township: NENW 7 34N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Holman Canyon 2  
Location ID: 306765



**Photo 1.** View of well disturbance taken from the access point facing center.



Inspection Photos  
Location Name: Holman Canyon 2  
Location ID: 306765



**Photo 2.** Scotch thistle in the interim reclamation areas have been removed/treated.





Inspection Photos  
Location Name: Holman Canyon 2  
Location ID: 306765



**Photo 3.** Impacted surface material has been removed from around well head.



Inspection Photos  
Location Name: Holman Canyon 2  
Location ID: 306765





Inspection Photos  
Location Name: Holman Canyon 2  
Location ID: 306765

