

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 32-12 Pad

Location ID: 324061



Photo # 9791 From entrance to location




Photo # 9792 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 32-12 Pad

Location ID: 324061



Photo # 9793 Location



Photo # 9794 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 32-12 Pad

Location ID: 324061



Photo # 9795 Location



Photo # 9796 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 32-12 Pad

Location ID: 324061



Photo # 9797 Location



Photo # 9798 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 32-12 Pad

Location ID: 324061



Photo # 9799 Location



Photo # 9800 Location



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 32-12 Pad

Location ID: 324061



Photo # 9801 Location



Photo # 9802 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 32-12 Pad

Location ID: 324061



Photo # 9803 Location



Photo # 9804 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 32-12 Pad

Location ID: 324061



Photo # 9805 Location



Photo # 9806 Chemical tank label damaged & some info is starting to become illegible (additionally chemical tanks on location do not appear to be listed on operators FORM 2A or FORM 4/not in compliance with CECMC rules)



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 32-12 Pad

Location ID: 324061



**Photo # 9807 Secondary containment does not comply with CECMC secondary containment rules. (Additionally 80 bbl tank does not appear to be in operators Form 2A or any Form 4 Sundry as required by CECMC rules)**



**Photo # 9808 Secondary containment does not comply with CECMC secondary containment rules. (Additionally 80 bbl tank does not appear to be in operators Form 2A or any Form 4 Sundry as required by CECMC rules)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 32-12 Pad

Location ID: 324061



**Photo # 9809 Summit Midstream meter house is not listed in operators FORM 2A/not in compliance with CECMC rules**



**Photo # 9810 Qnergy natural gas generator & air compressor not listed in operators FORM 2A or a FORM 4 SUNDRY/not in compliance with CECMC rules**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 32-12 Pad

Location ID: 324061



**Photo # 9811 YOUNBERG SR 411-12 bradenhead line tied into separator (valves shut at time of inspection)**



**Photo # 9812 YOUNBERG SR 411-12 bradenhead line tied into separator (valves shut at time of inspection)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 32-12 Pad

Location ID: 324061



**Photo # 9813 YOUNBERG SR 411-12 bradenhead line tied into separator (valves shut at time of inspection)**



**Photo # 9814 ECD does not appear to be listed on FORM 2A or FORM 4/not in compliance with CECMC rules**