

Inspection Photos

API: 071-07470

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 11/18/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north toward the wellsite. There appears to be an unknown spill.



Inspection Photos




Photo 2. This whit spill needs to be cleaned up.



Inspection Photos



Photo 2. Well sign is posted at meter shed..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-07470 | Date: 11/18/2024