

Caerus
Chevron 42-7D
Location ID: 335652



Location



Location

Caerus
Chevron 42-7D
Location ID: 335652



Location




Location

Caerus
Chevron 42-7D
Location ID: 335652



Location



Unused equipment

Caerus
Chevron 42-7D
Location ID: 335652



Lack of stabilization/ compaction



Location and Lack of stabilization/ compaction

Caerus
Chevron 42-7D
Location ID: 335652



Lack of stabilization/ compaction




Lack of stabilization/ compaction

Caerus
Chevron 42-7D
Location ID: 335652



Open pipe



Open pipe