

Inspection Photos

API: 071-07825

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 11/18/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the wellsite.



Inspection Photos



Photo 2. Well sign is posted at meter shed.



Inspection Photos



Photo 3. Facing east at the access road. This area will need maintenance.

