

# Inspection Photos

November 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326076

Inspection Document #: 714001500

La Plata County, CO

Township: NWSE 4 34N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Smith A 1  
Location ID: 326076



Photo 1. View of well disturbance taken from the access point facing center.



API #: 067-07431



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Smith A 1  
Location ID: 326076





Inspection Photos  
Location Name: Smith A 1  
Location ID: 326076



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Gully erosion on the southern edge of the pad.

API #: 067-07431



Inspection Photos  
Location Name: Smith A 1  
Location ID: 326076



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Reference area composed of Sagebrush, Broom Snakeweed and Western Wheatgrass.

API #: 067-07431