

Inspection Photos
Location Name: RAY-GLO-66N64W/14NENW
Location ID: 323413



Photo #1
Ray-Glo #1 (123-12985) Wellsite
Temporarily Abandoned | TA
OOSLAT tag needed



Photo #2
Ray-Glo #1 Battery site
Inactive | Shut-down
Equipment Documented; Loc ID: 323413



Inspection Photos

Location Name: RAY-GLO-66N64W/14NENW

Location ID: 323413



Photo #3

Ray-Glo #1 Battery site

Inactive | Shut-down

Well, Battery site entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources