

# Inspection Photos

November 20th, 2024

Operator: Simcoe LLC - 10749

Location ID: 312114

Inspection Document #: 714001513

La Plata County, CO

Township: NENE 7 32N 6W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HC McDonald 1  
Location ID: 312114

11/20/24  
350° N



Photo 1. View of well disturbance taken from the southern edge facing center.

Inspection Photos  
Location Name: HC McDonald 1  
Location ID: 312114

11/20/24  
14° N



**Photo 2.** Fence around produced water tank is in working order.

Inspection Photos  
Location Name: HC McDonald 1  
Location ID: 312114

11/20/24  
279° W



**Photo 3.** Placard/sign at separator is starting to deteriorate, future maintenance is advised.

Inspection Photos  
Location Name: HC McDonald 1  
Location ID: 312114

11/20/24  
335° NW



**Photo 4.** No stormwater issues observed on the active pad.