

Inspection Photos
Love Ranch Centralized E&P Waste Management Facility & Release
Facility ID: 149012 & Spill/Release ID: 487951
Inspection Date: November 20, 2024



Photo #1 – Parking to access the Pit Facility was located on an adjacent pad.

Photo #2 – Overview of pit from the north. Note: hydrocarbons observed on pit liner.

Inspection Photos
Love Ranch Centralized E&P Waste Management Facility & Release
Facility ID: 149012 & Spill/Release ID: 487951
Inspection Date: November 20, 2024



Photo #3 – Overview of pit from east, note debris and equipment (hoses) present on liner in northeast corner.

Photo #4 – Damaged section of liner in SW corner of pit.

Inspection Photos
Love Ranch Centralized E&P Waste Management Facility & Release
Facility ID: 149012 & Spill/Release ID: 487951
Inspection Date: November 20, 2024



Photo #5 – Stained soil (E&P Waste) located on pit berm (1).

Photo #6 - Stained soil (E&P Waste) located on pit berm (2).

Inspection Photos
Love Ranch Centralized E&P Waste Management Facility & Release
Facility ID: 149012 & Spill/Release ID: 487951
Inspection Date: November 20, 2024



Photo #7 - Stained soil (E&P Waste) located on pit berm (3).

Photo #8 - Stained soil (E&P Waste) located on pit berm (4).

Inspection Photos
Love Ranch Centralized E&P Waste Management Facility & Release
Facility ID: 149012 & Spill/Release ID: 487951
Inspection Date: November 20, 2024



Photo #9 – Unused equipment on pit berm.

Photo #10 – Unused equipment on pit berm (2).