

Inspection Photos

Location Name: CAERUS PICEANCE LLC, LONG RIDGE/J15 595

Location ID: 335568

Date: 11/21/2024



Location – Photo #05044



Location – Photo #05045

Inspection Photos

Location Name: CAERUS PICEANCE LLC, LONG RIDGE/J15 595

Location ID: 335568

Date: 11/21/2024



Location – Photo #05049



Location – Photo #05046

Inspection Photos

Location Name: CAERUS PICEANCE LLC, LONG RIDGE/J15 595

Location ID: 335568

Date: 11/21/2024



Tank Not Labeled/Corroding Paint – Photo #05047



Tank Not Labeled/Corroding Paint – Photo #05048