

Inspection Photos

November 20th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 306752

Inspection Document #: 714001527

La Plata County, CO

Township: SWSW 8 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Penrose 1 RX
Location ID: 306752

11/20/24
191° S



Photo 1. View of well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Penrose 1 RX
Location ID: 306752

11/20/24
108° E



Photo 2. View of northern interim reclamation area facing eastern. Vegetation is progressing with establishment of desirable vegetation including but not limited to Intermediate Wheatgrass, Grama and Crested Wheatgrass.

Inspection Photos
Location Name: Penrose 1 RX
Location ID: 306752



Photo 3. Topsoil signs have fallen over.

Inspection Photos
Location Name: Penrose 1 RX
Location ID: 306752

11/20/24
224° SW



Photo 4. Rutting occurring on active pad.

Inspection Photos
Location Name: Penrose 1 RX
Location ID: 306752



Photo 5. Weedy Russian Thistle and Kochia debris observed in the interim reclamation areas and throughout the active pad. Manage/remove weeds to promote further establishment of desirable vegetation in interim reclamation areas.

Inspection Photos
Location Name: Penrose 1 RX
Location ID: 306752

