

Inspection Photos

November 20th, 2024

Operator: Logos Operating LLC - 10679

Location ID: 306978

Inspection Document #: 714001529

La Plata County, CO

Township: NWNW 18 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



11/20/24
254° W

Photo 1. View of well disturbance taken from the access point facing center.



11/20/24
283° W



Inspection Photos
Location Name: Olguin 1A
Location ID: 306978

11/20/24
138° SE



11/20/24
56° NE

