

# Inspection Photos

November 20th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325592

Inspection Document #: 714001530

La Plata County, CO

Township: NESE 8 32N 6W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Payne 1-8 1  
Location ID: 325592

11/20/24  
148° SE



**Photo 1.** View of well disturbance taken from the access point facing center.



Inspection Photos  
Location Name: Payne 1-8 1  
Location ID: 325592

11/20/24  
321° NW





Inspection Photos  
Location Name: Payne 1-8 1  
Location ID: 325592

11/20/24  
306° NW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Placard/Sign at separator deteriorating and illegible.

API #: 067-06663



Inspection Photos  
Location Name: Payne 1-8 1  
Location ID: 325592



11/20/24  
36° NE



Inspection Photos

Location Name: Payne 1-8 1

Location ID: 325592



Photo 5. Impacted surface material observed at well head.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-06663



Inspection Photos  
Location Name: Payne 1-8 1  
Location ID: 325592



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 6.** Irrigated grass field/pasture reference area.

API #: 067-06663