

Inspection Photos

November 20th, 2024

Operator: Morning Star Operating LLC - 10755

Location ID: 333798

Inspection Document #: 714001532

La Plata County, CO

Township: SWNW 4 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

11/20/24
136° SE



Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Padgett 32-6 4-2, 4
Location ID: 333798

11/20/24
27° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Eastern interim reclamation area composed of Intermediate Wheatgrass and Rubber Rabbitbrush.

API #: 067-08660, 09463

Inspection Photos
Location Name: Padgett 32-6 4-2, 4
Location ID: 333798



Photo 3. Produced water tank signs/placards have been installed/updated.

Inspection Photos
Location Name: Padgett 32-6 4-2, 4
Location ID: 333798



Photo 4. Wildlife BMP netting/wiring at chemical container secondary containment is damaged and no longer functioning.

Inspection Photos
Location Name: Padgett 32-6 4-2, 4
Location ID: 333798



11/20/24
146° SE

Photo 5. View of active horse pasture reference area with predominantly grazed vegetation.