

Inspection Photos

November 20th, 2024

Operator: Morning Star Operating LLC - 10755

Location ID: 333339

Inspection Document #: 714001533

La Plata County, CO

Township: SESW 4 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Padgett 32-6 4-1, 3
Location ID: 333339

11/20/24
318° NW



Photo 1. View of the well disturbance taken from the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09494, 08976

Inspection Photos
Location Name: Padgett 32-6 4-1, 3
Location ID: 333339



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Southern interim reclamation area composed of Western Wheatgrass, Crested Wheatgrass and Rubber Rabbitbrush.

API #: 067-09494, 08976

Inspection Photos
Location Name: Padgett 32-6 4-1, 3
Location ID: 333339



Photo 3. Produced water tank signs/placards have been installed/updated.

11/20/24
65° NE

