

Inspection Photos

Location: LARAMIE ENERGY LLC Mesa/18-2 Pad

Location ID: 312636

Date: 11/21/2024



Photo # 9583 Entrance to location



Photo # 9609 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Mesa/18-2 Pad

Location ID: 312636

Date: 11/21/2024



Photo # 9584 Location



Photo # 9589 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Mesa/18-2 Pad

Location ID: 312636

Date: 11/21/2024



Photo # 9604 Location



Photo # 9608 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Mesa/18-2 Pad

Location ID: 312636

Date: 11/21/2024



Photo # 9653 NE corner of location



Photo # 9654 SE corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Mesa/18-2 Pad

Location ID: 312636

Date: 11/21/2024



Photo # 9655 SW corner of location




Photo # 9656 SW corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Mesa/18-2 Pad

Location ID: 312636

Date: 11/21/2024



Nov 21, 2024 at 1:37:00 PM
+38.278600, -108.258529 ±4.74m
De Beque



Nov 21, 2024 at 1:57:01 PM
+38.278346, -108.258212 ±4.74m
De Beque

Photo # 9598 Gas meter building roof paneling is damaged/wildlife hazard available for entry by wildlife

Photo # 9618 Subsidence in multiple areas on east side of location is also a wildlife/personnel safety hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Mesa/18-2 Pad

Location ID: 312636

Date: 11/21/2024



Photo # 9620 Subsidence in multiple areas on east side of location is also a wildlife/personnel safety hazard

Photo # 9621 Subsidence in multiple areas on east side of location is also a wildlife/personnel safety hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Mesa/18-2 Pad

Location ID: 312636

Date: 11/21/2024



Photo # 9635 Subsidence in multiple areas on east side of location is also a wildlife/personnel safety hazard

Photo # 9639 Subsidence in multiple areas on east side of location is also a wildlife/personnel safety hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Mesa/18-2 Pad

Location ID: 312636

Date: 11/21/2024



Photo # 9644 Subsidence in multiple areas on east side of location is also a wildlife/personnel safety hazard



Photo # 9649 Subsidence in multiple areas on east side of location is also a wildlife/personnel safety hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Mesa/18-2 Pad

Location ID: 312636

Date: 11/21/2024



Photo # 9600 Chemical tank is not labeled



Photo # 9601 Chemical tank is not labeled