

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, LONG RIDGE/M15 595

Location ID: 335865

Date: 11/21/2024



Northwest Corner of Location – Photo #05053



Location – Photo #05052

## Inspection Photos


Location Name: CAERUS PICEANCE LLC, LONG RIDGE/M15 595

Location ID: 335865

Date: 11/21/2024



Location – Photo #05055



Location – Photo #05054





## Inspection Photos

Location Name: CAERUS PICEANCE LLC, LONG RIDGE/M15 595

Location ID: 335865

Date: 11/21/2024



Wildlife Entry Hazard – Photo #05056



Wildlife Entry Hazard – Photo #05057