ENTRADA

SITE NAME: Hoffman CO2-65HN	DATE: 9/26/24 WEATHER: clear
GENERAL CONDITION OF SITE: Overgrown	CLIENT: Chevron
LAT/LONG:	PERSONNEL: I. Lohrer, C. Clifford
ESTIMATED DEPTH TO GROUNDWATER:	OTHER OBSERVATIONS:

SOIL SAMPLING

Date	Soil Sample ID	Soil Type	PID (ppm)	Staining (Y/N)	Odor (Y/N)	Time
9/26	WH01@6	SM	1.6	N	N	1000
	FLR01@4		1.7			1005
	WH01-N@4		3.7			1010
	WH01-E@4		2.4			1015
	WH01-W@4		3.2			1020

GROUNDWATER SAMPLING

Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?

FACILITY INFRASTRUCTURE

EQUIPMENT	Quantity
Above Ground Storage Tank (AST)	0
Buried or Partially Buried Vessel	0
Separator	0
Emission Control Device (ECD)	0
Dump Line	0
Wellhead	1
Flowline	1
Third Party Equipment:	
Other:	

Soil Loads Removed

IMPACTED SOIL IDENTIFIED?

ESTIMATED VOLUME OF IMPACTS:

Date	Number	CY
Total Removed		

Disposal Facility:

Groundwater Recovery

DATE GW ENCOUNTERED:	DEPTH:

GROUNDWATER IN CONTACT WITH IMPACTED SOIL?

LNAPL OR SHEEN OBSERVED ON GW?

Date	BBLS
Total Removed	

Disposal Facility: