

Inspection Photos

November 1st, 2024

Operator: Morningstar Operating - 10755

Location ID: 333344

Inspection Document #: 714001430

Archuleta County, CO

Township: Lot 4 6 32N 5W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Quintana 32-5 6-1, 4
Location ID: 333344

11/1/24
278° W



Photo 1. View of well disturbance taken from the access point facing center. Note: Well location signs are missing location emergency services contact information.

Inspection Photos
Location Name: Quintana 32-5 6-1, 4
Location ID: 333344



Photo 2. View of legible produced water tank signage/labels.

Inspection Photos
Location Name: Quintana 32-5 6-1, 4
Location ID: 333344



Photo 3. View of erosion issues occurring in the northern portion of the disturbance.

Inspection Photos
Location Name: Quintana 32-5 6-1, 4
Location ID: 333344



Photo 4. View of trash/debris in the northern corner of the disturbance.

Inspection Photos

Location Name: Quintana 32-5 6-1, 4

Location ID: 333344

11/1/24
215° SW



Photo 5. Large patch of flowered/seeded Musk Thistle on the western edge of the disturbance.