

Inspection Photos

November 20th, 2024

Operator: Logos Operating LLC - 10679

Location ID: 325009

Inspection Document #: 714001528

La Plata County, CO

Township: SWNE 18 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Olguin 1
Location ID: 325009



11/20/24
203° SW



Photo 1. View of well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Olguin 1
Location ID: 325009



Photo 2. Dense weedy debris observed on location.

Inspection Photos
Location Name: Olguin 1
Location ID: 325009

11/20/24
83° E



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Rutting on active pad. Additional stabilization/grading needed. Note: unused equipment remains on location.

API #: 067-05078

Inspection Photos
Location Name: Olguin 1
Location ID: 325009

11/20/24
224° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Southern interim reclamation area composed of Sagebrush, Intermediate Wheatgrass and Crested Wheatgrass.

API #: 067-05078

Inspection Photos
Location Name: Olguin 1
Location ID: 325009

11/20/24
140° SE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed of Sagebrush, Indian Ricegrass and Juniper.

API #: 067-05078