

# Inspection Photos

September 9th, 2024

Operator: BP American Production Co - 10000

Location ID: 325646

Inspection Document #: 714001540

La Plata County, CO

Township: SENW 24 33N 10W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Craig 2E  
Location ID: 325646

9/9/24  
+37.091876,-107.888858  
338° N



**Photo 1.** View of the well disturbance taken from the access point facing center.

Inspection Photos  
Location Name: Craig 2E  
Location ID: 325646



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of western cut slope area that remains with bare soil and minimal vegetation.

API #: 067-06765

Inspection Photos  
Location Name: Craig 2E  
Location ID: 325646



**Photo 3.** Eastern cut slope that appears vegetation to 80% vegetation threshold with Rubber Rabbitbrush, Smooth Brome and Juniper.

Inspection Photos  
Location Name: Craig 2E  
Location ID: 325646



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Reference area composed of Smooth Brome, Juniper and Grama sp.

API #: 067-06765