

**Inspection Photos**  
**Location Name: QB Energy SHIDELER 19-8 (H19) Pad**  
**Location ID: 334886**



**Photo # 1698 From entrance to location**



**Photo # 1699 From entrance to location**

Inspection Photos  
Location Name: QB Energy SHIDELER 19-8 (H19) Pad  
Location ID: 334886




Photo # 1700 Location

Photo # 1701 Location

**Inspection Photos**  
**Location Name: QB Energy SHIDELER 19-8 (H19) Pad**  
**Location ID: 334886**



**Photo # 1702 Location**



**Photo # 1703 Location**

Inspection Photos  
Location Name: QB Energy SHIDELER 19-8 (H19) Pad  
Location ID: 334886



Photo # 1704 Location




Photo # 1705 Location

**Inspection Photos**  
**Location Name: QB Energy SHIDELER 19-8 (H19) Pad**  
**Location ID: 334886**



**Photo # 1706 Location**



**Photo # 1707 Location**

**Inspection Photos**  
**Location Name: QB Energy SHIDELER 19-8 (H19) Pad**  
**Location ID: 334886**



**Photo # 1708 Flowline heating insulation open ended  
/wildlife hazard/available for entry by wildlife**



**Photo # 1709 Flowline heating insulation damaged/wildlife  
hazard/available for entry by wildlife**