

Inspection Photos

Location Name: Bridle Federal 44-2

Location ID: 323939

Inspection Date: 11/14/2024

Location sign.



Nov 14, 2024 1:18:54 PM  
+39.3921N -108.9545W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos

Location Name: Bridle Federal 44-2

Location ID: 323939

Inspection Date: 11/14/2024

Bridle Federal 44-2  
location.

Nov 14, 2024 1:19:02 PM  
+39.3922N -108.9544W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos

Location Name: Bridle Federal 44-2

Location ID: 323939

Inspection Date: 11/14/2024

Wellhead.

Nov 14, 2024 1:19:19 PM  
+39.3922N -108.9542W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos

Location Name: Bridle Federal 44-2

Location ID: 323939

Inspection Date: 11/14/2024

Location of the active gas leak at the wellhead.

Nov 14, 2024 1:19:49 PM  
+39.3922N -108.9542W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources