

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404008890

Date Received:

11/26/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001452

Inspection Date: 11/06/2024

FIR Submit Date: 11/13/2024

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 333866

Location Name: BELLINO GAS UNIT-M34N8W Number: 30SWNE County: _____

Qtrqtr: SWNE Sec: 30 Twp: 34N Range: 8W Meridian: M

Latitude: 37.165565 Longitude: -107.758112

FACILITY - API Number: 05-067- -00 Facility ID: 333866

Facility Name: BELLINO GAS UNIT-M34N8W Number: 30SWNE

Qtrqtr: SWNE Sec: 30 Twp: 34N Range: 8W Meridian: M

Latitude: 37.165565 Longitude: -107.758112

CORRECTIVE ACTIONS:

1 CA# 200413

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 906 and 1002.

Date: 11/18/2024

Response: CA COMPLETED

Date of Completion: 11/25/2024

Operator Comment: Impacted soil removed.

ECMC Decision: _____

Date: 11/26/2024 6:39:38 PM

Total Attach: 2 Files