

Inspection Photos

Loc: 324505

Operator: **OXY USA INC**

Inspection Date: 11/25/2024

County: Huerfano



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north toward the location. The remediation project has been completed but final reclamation was not performed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324505 | Date: 11/25/2024

Inspection Photos



Photo 2. The lined pit remains at the location and must be closed per approved form 27.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:324505 | Date: 11/25/2024

Inspection Photos



Photo 3. Facing south at the location. The location will need to be recontoured per 1004 Rule..



Inspection Photos



Photo 4. Facing southeast along the fill slope which will need to be partly recontoured. There are active wells that remain on the lower pad and far southeast side.

