

Operator: Extraction Oil & Gas Inc

Location Name: Casa Loma 4-25

Loc ID: 430703

Inspection: 697010402



Exhibit A




Exhibit B



Exhibit C



Exhibit D

CA: Crude oil tanks contents/capacity placards have faded and are illegible, see attached photos. Install sign to comply with Rule 605.h.

CA Resolution: The operator has provided photo evidence showing that signs indicating contents and capacity, along with updated placards, have been installed to comply with Rule 605.h.