



99999999

**OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION REPORT**☒ NOTICE OF UNSATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801

Denver, CO 80203

(303)894-2100

☐ NOTICE OF SATISFACTORY INSPECTIONAPI No. 05- *121-08509*LEASE NAME: *Fassler 1-A*LOCATION: *SE NW 33 - 2N - 53*OPERATOR: *Doherty*DATE: *10-6-95*INSPECTOR: *Ed Binkley*Insp. Type: *Pr*Insp. Status: *Pr*

PA: Y

N

Pass/Fail: P

*F*

Viol.: Y

N

NOV: Y

*N***INSPECTION ITEM****COMMENTS****INPUT**

<b>Well ID Signs</b> (Rule 210)	<b>SCANNED</b>	
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904)		
<b>Fences</b> (Rule 604.C.(3), 1003.A)		
<b>Tank Battery Equipment</b> (Rule 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 604)	<i>No tank berms</i>	
<b>General Housekeeping</b> (Rule 603.G)		
<b>Spills (Oil/Water)</b> (Rule 908)		
<b>Bradenhead</b> (Rule 207)		
<b>Drilling Well/Workover</b> (Rule 315)		
<b>Surface Rehabilitation</b> (Rule 317)		
<b>Miscellaneous</b>		

**CORRECTIVE ACTION REQUIRED:** *Install tank berms.*Date Corrective Action Required By: *11-6-95*

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site



00047886