

## Inspection Photos

Location: LARAMIE ENERGY LLC Castle Rock/7-14 Pad

Location ID: 312653

Date: 11/21/2024



Photo # 9729 Entrance to location



Photo # 9749 Location

## Inspection Photos

Location: LARAMIE ENERGY LLC Castle Rock/7-14 Pad

Location ID: 312653

Date: 11/21/2024



Photo # 9730 Location



Photo # 9735 Location

## Inspection Photos

Location: LARAMIE ENERGY LLC Castle Rock/7-14 Pad

Location ID: 312653

Date: 11/21/2024



Photo # 9748 Location



Photo # 9755 SW corner of location

## Inspection Photos

Location: LARAMIE ENERGY LLC Castle Rock/7-14 Pad

Location ID: 312653

Date: 11/21/2024



Photo # 9756 NW corner of location



Photo # 9757 NE corner of location

## Inspection Photos

Location: LARAMIE ENERGY LLC Castle Rock/7-14 Pad

Location ID: 312653

Date: 11/21/2024



Photo # 9758 SE corner of location



Photo # 9744 Gas meter building roof paneling is damaged/wildlife hazard available for entry by wildlife