

Inspection Photos

Location: LARAMIE ENERGY LLC Blackman/14-12 Pad

Location ID: 334544

Date: 11/25/2024



Photo # 9917 Entrance to location




Photo # 9927 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Blackman/14-12 Pad

Location ID: 334544

Date: 11/25/2024



Nov 25, 2024 at 3:05:11 PM
+39.273016,-107.855752 ±4.72m
Collbran

Photo # 9918 Location



Nov 25, 2024 at 3:08:07 PM
+39.273081,-107.856042 ±4.73m
Collbran

Photo # 9919 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Blackman/14-12 Pad

Location ID: 334544

Date: 11/25/2024



Photo # 9920 Location



Photo # 9926 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Blackman/14-12 Pad

Location ID: 334544

Date: 11/25/2024



Photo # 9949 SW corner of location



Photo # 9950 NW corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Blackman/14-12 Pad

Location ID: 334544

Date: 11/25/2024



Photo # 9953 Weeds/undesirable plant species on location



Photo # 9254 Weeds/undesirable plant species on location

Inspection Photos

Location: LARAMIE ENERGY LLC Blackman/14-12 Pad

Location ID: 334544

Date: 11/25/2024



Photo # 9957 Weeds/undesirable plant species on location



Photo # 9958 Weeds/undesirable plant species on location



Inspection Photos
Location: LARAMIE ENERGY LLC Blackman/14-12 Pad
Location ID: 334544
Date: 11/25/2024



Photo # 9959 Weeds/undesirable plant species on location



Photo # 9960 Weeds/undesirable plant species on location

Inspection Photos

Location: LARAMIE ENERGY LLC Blackman/14-12 Pad

Location ID: 334544

Date: 11/25/2024



Photo # 9962 Weeds/undesirable plant species on location



Photo # 9944 Multiple holes in secondary containment liner/liner needs maintenance

Inspection Photos

Location: LARAMIE ENERGY LLC Blackman/14-12 Pad

Location ID: 334544

Date: 11/25/2024



Photo # 9947 Multiple holes in secondary containment liner/liner needs maintenance



Photo # 9948 Multiple holes in secondary containment liner/liner needs maintenance