


Inspection Photos
Operator: CAERUS PICEANCE LLC – 10456
Location Name: PICEANCE CREEK UNIT # T36-3X WWD
Location ID: 315897 API #: 05-103-09404
Inspection Date: 12/2/2024 Inspection Doc#: 693807912



Injection Wellhead during MIT



Form 21 field copy