

# Inspection Photos

11/12/2024

**Operator:** LARAMIE ENERGY LLC #10433

**Location ID:** 442549

**Inspection Doc:** 718100015

Mesa County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 442549



**Photo 1:** Photos examples showing BMPs to stabilize the working pad surface are in disrepair. Degradation and tracking observed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 442549



**Photo 2:** Photos examples showing BMPs to stabilize the working pad surface are in disrepair. Degradation and tracking observed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources