

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/26/2024

Submitted Date:

11/26/2024

Document Number:

714201911**FIELD INSPECTION FORM**Loc ID 418415 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418414	WELL	PA	01/25/2024	OW	123-31920	Dechant X 01-07	PA

General Comment:

This is an audit of DECHANT X 01-07 scout card and related documents followed by a field inspection.

LocationOverall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	unused/disconnected gas meter. See attached photo.		
Corrective Action:	Comply with Rule 603.m.	Date:	12/26/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 418414

Type: WELL

API Number: 123-31920

Status: PA

Insp. Status: PA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: SITE CONDITION

Comment: PA; Form 6(S) in well file.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<div>ECMC Inspection Report Summary</div> <div>WEATHER CONDITIONS: cloudy, dry ground.</div> <div>On Tuesday, November 26, 2024 at approximately 1430, I, Inspector Brittani Santistevan, conducted an on-site inspection at DECHANT X 01-07 (Noble Energy, Inc.), at location ID: 418415 in WELD COUNTY, Colorado.</div> <div>While there, I observed a plugged and abandoned location.</div> <div>During this inspection the following possible compliance issues were observed:</div> <div>1. It appears to be an unused/disconnected gas meter still on the tank battery location.</div> <div>Remove to comply with Rule 603.m. (Corrective Action Date: January 26, 2024) See attached photo #2.</div> <div>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</div> <div>This is a summary of inspection report.</div>	santistb	11/26/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404008743	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6802689
714201912	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6802652