

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403975047
Receive Date:
11/01/2024

Report taken by:
Kari Brown

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Operator No: <u>47120</u>	Phone Numbers
Address: <u>P O BOX 173779</u>		Phone: <u>(713) 350-4906</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-3779</u>		Mobile: <u>()</u>
Contact Person: <u>Ariana Ochoa</u>	Email: <u>DJRemediation_Forms@oxy.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 31824 Initial Form 27 Document #: 403497258

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

Yes Multiple Facilities

Facility Type: <u>LOCATION</u>	Facility ID: <u>336287</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>LDS-63N68W 24SWSE</u>	Latitude: <u>40.206150</u>	Longitude: <u>-104.949510</u>	
	** correct Lat/Long if needed: Latitude: <u>40.208669</u>	Longitude: <u>-104.951094</u>	
QtrQtr: <u>SWSE</u> Sec: <u>24</u> Twp: <u>3N</u> Range: <u>68W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>			

Facility Type: <u>SPILL OR RELEASE</u>	Facility ID: <u>485907</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>LDS 16-24, Presiding O SA Facility</u>	Latitude: <u>40.208669</u>	Longitude: <u>-104.951094</u>	
	** correct Lat/Long if needed: Latitude: _____	Longitude: _____	
QtrQtr: <u>NWSE</u> Sec: <u>24</u> Twp: <u>3N</u> Range: <u>68W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>			

SITE CONDITIONS

General soil type - USCS Classifications SM

Most Sensitive Adjacent Land Use Surface Water

Is domestic water well within 1/4 mile? No

Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

Irrigation ditch 50 feet (ft) west and 170 ft north. Occupied building 610 ft south. Livestock 680 ft south. Agriculture. Groundwater encountered at approximately 11 ft below ground surface (bgs).

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- E&P Waste Other E&P Waste Non-E&P Waste
- Produced Water Workover Fluids
- Oil Tank Bottoms
- Condensate Pigging Waste
- Drilling Fluids Rig Wash
- Drill Cuttings Spent Filters
- Pit Bottoms
- Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	TBD	Groundwater Samples/Laboratory Analytical Results
Yes	SOILS	TBD	Soil Samples/Laboratory Analytical Results

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Decommissioning activities were completed at the LDS 16-24, Presiding O SA Facility on January 2 and January 4, 2024. Visual inspection and field screening of soil at four aboveground storage tanks (ASTs), one produced water vessel (PWV), three separators, one emission control device (ECD), four dumphine potholes, and one meter house location were conducted following removal activities. Soil samples (AST01@0.5', AST02@0.5', AST03@0.5', AST04@0.5', PWV-B01@4', PWV-N01@2', SEP01-INLET@4', SEP01-OUTLET@3', SEP02-INLET@4', SEP02-OUTLET@3', SEP03-INLET@4', & SEP03-OUTLET@3') were submitted for analysis of full list Table 915-1 constituents, to determine if a release occurred. Laboratory analytical results indicated that benzo(a)anthracene, 1-methylnaphthalene, sodium adsorption ratio (SAR), pH, boron, arsenic, barium, cadmium, and/or hexavalent chromium impacts exceeding the ECMC Table 915-1 allowable levels or background levels were present at the ASTs, PWV, SEP01 and SEP02 locations. As such, Form 19 Initial/Supplemental Spill/Release Report (Document # 403646804) was submitted on January 8, 2024, and the ECMC issued Spill/Release Point ID 485907. Verification samples were collected to confirm the initial results at AST03, SEP01-OUTLET, SEP03-OUTLET, PWV-B01, and PWV-N01. Results for the verification samples were within the Table 915-1 allowable levels or background levels except for AST03 and SEP01-OUTLET. The soil sample and field screening locations are illustrated on Figures 1A & 1B. The PID readings and soil sample results are summarized in Tables 1 and 2, respectively.

Excavation activities are ongoing and will be summarized in a subsequent Form 27 Supplemental report.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Between January 2 and May 31, 2024, excavation activities were conducted to address remaining soil impacts at the former tank battery and separator locations. Confirmation soil samples were collected from the base and sidewalls of the excavations at depths ranging from 2.5 to 11 ft bgs. The confirmation soil samples were submitted for laboratory analysis of the site-specific waste profile including total petroleum hydrocarbons (TPH), benzene, toluene, ethylbenzene, xylenes (BTEX), trimethylbenzenes (TMBs), naphthalene, polycyclic aromatic hydrocarbons (PAHs), SAR, boron, and/or select Table 915-1 metals, using ECMC-approved methods. Laboratory analytical results indicate pH impacts above the ECMC Table 915-1 allowable level and site-specific background level remain at the AST-B02@2.5' location. Assessment activities are ongoing. The laboratory reports are attached.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

On February 29, 2024, one groundwater sample was collected from the separator excavation (GW01). The sample was submitted for laboratory analysis of full list Table 915-1 constituents in groundwater. Based on the laboratory analytical results, groundwater concentrations were in full compliance with ECMC Table 915-1 allowable levels for Table 915-1 organic constituents, chloride, and sulfate. Background groundwater samples are needed to assess inorganic compliance of Total Dissolved Solids (TDS). The excavation groundwater sample location is depicted on Figure 1B. The groundwater sample analytical results are summarized in Table 3.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

On January 5, 2024, visual inspections and field screening of soils were conducted at the hatch and loadout for all the ASTs, three sidewalls of the PWV excavation, four pothole dumphine locations, the ECD, and the meter house. Based on the inspection and screening results, hydrocarbon-impacted soils were not observed at the soil screening locations. As a result, no soil samples were submitted for laboratory analysis from these areas in accordance with the ECMC Operator Guidance for Oil & Gas Facility Closure document. The soil sample locations are depicted on Figure 1A. A photographic log is attached.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 64
 Number of soil samples exceeding 915-1 62
 Was the areal and vertical extent of soil contamination delineated? No
 Approximate areal extent (square feet) 13390

NA / ND

-- Highest concentration of TPH (mg/kg) 826
 -- Highest concentration of SAR 25.7
 BTEX > 915-1 No
 Vertical Extent > 915-1 (in feet) 11

Groundwater

Number of groundwater samples collected 1
 Was extent of groundwater contaminated delineated? No
 Depth to groundwater (below ground surface, in feet) 11
 Number of groundwater monitoring wells installed 0
 Number of groundwater samples exceeding 915-1 0

ND Highest concentration of Benzene (µg/l) _____
 ND Highest concentration of Toluene (µg/l) _____
 ND Highest concentration of Ethylbenzene (µg/l) _____
 ND Highest concentration of Xylene (µg/l) _____
 NA Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected
 Number of surface water samples exceeding 915-1
 If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

One tank battery background soil sample (TB-BG01@0.5') was collected from the soil used to construct the tank battery for comparison to samples collected within the fill material. Twenty-six native background soil samples were collected from native material outside of the facility excavations. Fifty background samples were collected as part of the Presiding Bish Un 1, LDS 16, 39-24, and LDS 15-24 wellheads cut and cap activities (Rem Nos. 31778, 31702, 31784), located in the same quarter section and NRCS soil type. Background samples were submitted for laboratory analysis of pH, EC, SAR, boron, and/or select Table 915-1 metals. Laboratory analytical results indicate that arsenic is naturally high in the soil used to construct the tank battery, & pH, arsenic, barium, hexavalent chromium, lead, & selenium are naturally high in the native soil. The background soil sample analytical results are summarized in Table 2. The background soil sample locations are depicted on Figure 2.

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____ Volume of liquid waste (barrels) _____

Is further site investigation required?

Assessment activities are ongoing and will be summarized in a subsequent Form 27 Supplemental report.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Impacted soil will be removed and transported to a licensed disposal facility. Final disposal information will be provided upon completion of excavation activities. Disposal records will be kept on file and available upon request. The excavation areas will be backfilled and contoured to match pre-existing conditions.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Laboratory analytical results indicate pH impacts above the ECMC Table 915-1 allowable level and site-specific background level remain at the AST-B02@2.5' location. Groundwater was encountered in the separator excavation at approximately 11 ft bgs. Groundwater analytical results indicate that Table 915-1 organic constituents, chloride, and sulfate are in compliance with ECMC standards. Background groundwater samples are needed to determine TDS compliance. Assessment activities are ongoing and will be summarized in a subsequent Form 27 Supplemental report.

Soil Remediation Summary

In Situ

Ex Situ

_____ Bioremediation (or enhanced bioremediation)

_____ Excavate and offsite disposal

_____ Chemical oxidation

_____ If Yes: Estimated Volume (Cubic Yards) _____

_____ Air sparge / Soil vapor extraction

_____ Name of Licensed Disposal Facility or ECMC Facility ID # _____

_____ Natural Attenuation

_____ Excavate and onsite remediation

_____ Other _____

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Does Groundwater meet Table 915-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The site will be reclaimed in accordance with ECMC 1000 Series Reclamation Rules.

Is the described reclamation complete? _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim

Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 01/08/2024

Actual Spill or Release date, or date of discovery. 01/08/2024

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 01/02/2024

Proposed site investigation commencement. 01/02/2024

Proposed completion of site investigation. 04/30/2025

REMEDIAL ACTION DATES

Proposed start date of Remediation. 01/02/2024

Proposed date of completion of Remediation. 04/30/2025

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

No additional work has been done since the previous Form 27 and, as such, none of the previous attachments have been included with this form. The implementation schedule has been updated.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Ariana Ochoa

Title: Sr. HSE Advisor

Submit Date: 11/01/2024

Email: DJRemediation_Forms@oxy.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Kari Brown

Date: 12/03/2024

Remediation Project Number: 31824

COA Type**Description**

	ECMC has processed this form as an update; no analytical was attached thus approval of this form does not imply any agreement with comments on completion of site investigation. All ongoing/unaddressed comments/COAs from previous Forms remain applicable.
1 COA	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

403975047	FORM 27-SUPPLEMENTAL-SUBMITTED
-----------	--------------------------------

Total Attach: 1 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)