

Inspection Photos

11/12/2024

Operator: LARAMIE ENERGY LLC #10433

Location ID: 334427

Inspection Doc: 718100022

Mesa County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334427



Photo 1: Photo taken from the cut slopes on the south end of the Location, facing east. Limited inspection due to snow cover, however work to address the stormwater and reclamation issues appears to have been performed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334427



Photo 2: Photos 2-4 examples showing that the working pad surface lacks stabilization; BMPs to stabilize the pad, as well as to minimize erosion, degradation, and sediment transport have not been maintained in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 334427



Photo 3: See comments under photo 2.



Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334427



Photo 4: See comments under photo 2.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources