

Inspection Photos

11/12/2024

Operator: LARAMIE ENERGY LLC #10433

Location ID: 452797

Inspection Doc: 718100028

Mesa County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 452797



November 12, 2024



November 12, 2024

Photo 1: Photos examples showing that the BMPs to stabilize the working pad surface, as well as to minimize erosion, degradation, and sediment transport are in disrepair; tracking/degradation apparent.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 452797



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 452797



November 12, 2024

Photo 3: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 452797



Photo 4: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources