

Inspection Photos

11/12/2024

Operator: LARAMIE ENERGY LLC #10433

Location ID: 450760

Inspection Doc: 718100031

Mesa County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 450760



Photo 1: Photos 1-2 taken from the Location entrance on the west end of the Pad. Photos provide an overview of the Location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 450760



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 450760



Photo 3: Photos examples showing that the BMPs to stabilize the working pad surface, as well as to minimize erosion, degradation, and sediment transport are in disrepair; tracking/degradation apparent.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 450760



November 12, 2024



November 12, 2024

Photo 4: Photos 4-6 examples showing Noxious weeds observed on the Location. Species include Musk thistle, Canada thistle and Bull thistle.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 450760



Photo 5: See comments under photo 4.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 450760



Photo 6: See comments under photo 4.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources