

Inspection Photos

11/12/2024

Operator: LARAMIE ENERGY LLC #10433

Location ID: 450791

Inspection Doc: 718100035

Mesa County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 450791



Photo 1: Photos examples showing Noxious weeds (Bull thistle, Canada thistle) observed within interim areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 450791



Photo 2: Lines at tanks missing cap/plug.