

Inspection Photos
Location Name: Longmont Farms Unit 5
Location ID: 323578



Photo 1 Location.



Photo 2 Wellhead.

Inspection Photos
Location Name: Longmont Farms Unit 5
Location ID: 323578



Energy & Carbon Management Commission
40.10525, -104.99424, 4931.9ft, 203°
12/02/2024 14:24:19

Photo 3 Wellhead sign.



Energy & Carbon Management Commission
40.10528, -104.9943, 4924.5ft, 213°
12/02/2024 14:24:41

Photo 4 Wellsite.

Inspection Photos
Location Name: Longmont Farms Unit 5
Location ID: 323578



Photo 5 Pump jack.



Photo 6 Ancillary equipment.