

**Inspection Photos**  
**Location Name: Grant 3**  
**Location ID: 318532**



**Photo 1 Location**



**Photo 2 Wellhead over run with dead vegetation.**



**Inspection Photos**  
**Location Name: Grant 3**  
**Location ID: 318532**



**Photo 3 Trash is hidden by over grown vegetation at the WH.**



**Photo 4 Trash is hidden by over grown vegetation at the WH.**



**Inspection Photos**  
**Location Name: Grant 3**  
**Location ID: 318532**



**Photo 5 Over grown vegetation by the WH.**



**Photo 6 WH sign.**



**Inspection Photos**  
**Location Name: Grant 3**  
**Location ID: 318532**



**Photo 9 Over grown vegetation on location ROW.**



**Photo 10 Trash & dead vegetation on location ROW.**



**Inspection Photos**  
**Location Name: Grant 3**  
**Location ID: 318532**



**Photo 7 Over grown vegetation by the Electric panel.**



**Photo 8 Trash & dead vegetation by the ancillary equipment.**