

**Inspection Photos**  
**Location Name: Grant 4**  
**Location ID: 311319**



**Photo 1 Location, Dead vegetation in and outside of the wellsite fence.**



**Photo 2 Wellhead over run with dead vegetation.**



**Inspection Photos**  
**Location Name: Grant 4**  
**Location ID: 311319**



**Photo 3 Dead tall vegetation around the WH.**



**Photo 4 Over grown vegetation at the WH sign.**



**Inspection Photos**  
**Location Name: Grant 4**  
**Location ID: 311319**



**Photo 5 Dead vegetation between the pump jack and wellsite fence.**



**Photo 6 Dead vegetation between the pump jack and wellsite fence.**



**Inspection Photos**  
**Location Name: Grant 4**  
**Location ID: 311319**



**Photo 7 Over grown vegetation by the Electric panel & inside the pump jack fence.**



**Photo 8 Dead vegetation by the ancillary equipment.**