

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412



Nov 26, 2024 at 12:39:49 PM
CO



Nov 26, 2024 at 12:40:05 PM
CO

Photo # 1544 From entrance to location

Photo # 1545 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412




Photo # 1546 Location

Photo # 1547 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412



Photo # 1548 Location



Photo # 1549 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412



Photo # 1550 Location



Photo # 1551 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412



Photo # 1552 Location



Photo # 1553 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad

Location ID: 335412



Photo # 1554 RWF 543-18 wellhead sign peeling & some required info starting to become illegible




Photo # 1555 RWF 42-18 wellhead sign peeling & some required info starting to become illegible