

Inspection Photos

Location: LARAMIE ENERGY LLC Bruton/30-10 Pad

Location ID: 418985

Date: 12/2/2024



Photo # 0059 Entrance to location



Photo # 0076 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Bruton/30-10 Pad

Location ID: 418985

Date: 12/2/2024



Photo # 0060 Location



Photo # 0070 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Bruton/30-10 Pad

Location ID: 418985

Date: 12/2/2024




Photo # 0073 Location



Photo # 0075 Location



Inspection Photos

Location: LARAMIE ENERGY LLC Bruton/30-10 Pad

Location ID: 418985

Date: 12/2/2024



Photo # 0089 Location



Photo # 0090 SE corner of location



Inspection Photos

Location: LARAMIE ENERGY LLC Bruton/30-10 Pad

Location ID: 418985

Date: 12/2/2024



Photo # 0091 NE corner of location



Photo # 0092 NW corner of location



Inspection Photos

Location: LARAMIE ENERGY LLC Bruton/30-10 Pad

Location ID: 418985

Date: 12/2/2024



Photo # 0064 Loose barbed wire/wildlife hazard



Photo # 0065 Loose barbed wire/wildlife hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Bruton/30-10 Pad

Location ID: 418985

Date: 12/2/2024



Photo # 0086 Open ended load line



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources