

# Inspection Photos

November 1st, 2024

Operator: Petrox Resources INC - 69805

Location ID: 320905

Inspection Document #: 714001436

Archuleta County, CO

Township: NENW 16 34N 5W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Fosset Gulch 16U 1  
Location ID: 320905



11/1/24  
306° NW



11/1/24  
355° N

**Photo 1.** View of well disturbance taken from the access point facing center. Note: Local emergency contact # has been posted to the location sign.

Inspection Photos  
Location Name: Fosset Gulch 16U 1  
Location ID: 320905



Photo 2. View of weedy debris encroaching on well head.



Inspection Photos  
Location Name: Fosset Gulch 16U 1  
Location ID: 320905



**Photo 3.** Eastern side of the gravelled pad does not appear needed for production operations and has not been reclaimed per 1003 rules/requirements.

Inspection Photos

Location Name: Fosset Gulch 16U 1

Location ID: 320905



**Photo 4.** 2024 aerial imagery of the areas of the pad which have not been reclaimed to 1003 standards/requirements.

Inspection Photos  
Location Name: Fosset Gulch 16U 1  
Location ID: 320905



**Photo 5.** Reference area composed of Pine, Gambel Oak and Squirrel Tail.