

Inspection Photos

October 25th, 2024

Operator: Kinder Morgan - 46685

Location ID: 313601

Inspection Document #: 714001501

Montezuma County, CO

Township: NWNW 2 37N 18W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Yellow Jacket YE 7
Location ID: 313601



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the project area taken from the western edge facing center.

API #: 083-06624

Inspection Photos

Location Name: Yellow Jacket YE 7

Location ID: 313601



Photo 2. Cardinal photos taken from the center of the disturbance, left photo facing north, right photo facing east.

Inspection Photos
Location Name: Yellow Jacket YE 7
Location ID: 313601



Photo 3. Cardinal photos taken from the center of the disturbance, left photo facing south, right photo facing west. Note: seeded/reclaimed area appears consistent with adjacent reference area. See photo 6.

Inspection Photos
Location Name: Yellow Jacket YE 7
Location ID: 313601

10/25/24
2° N



Inspection Photos
Location Name: Yellow Jacket YE 7
Location ID: 313601



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of reclaimed access road taken from the northern edge facing south.

API #: 083-06624

Inspection Photos
Location Name: Yellow Jacket YE 7
Location ID: 313601



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Reference area composed predominantly of Big Sagebrush and Indian Ricegrass.

API #: 083-06624