

Inspection Photos

November 15th, 2024

Operator: Kinder Morgan - 46685

Location ID: 454998

Inspection Document #: 714001512

Montezuma County, CO

Township: Lot 13 10 38N 19W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CB 4
Location ID: 454998

11/15/24
140° SE



Photo 1. View of location/gravelled area taken from the northern edge facing center. Note: large portion of gravelled area remains and has not been interim reclaimed, see photo 4.

Inspection Photos
Location Name: CB 4
Location ID: 454998

11/15/24
176° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of western interim fill slope area. Vegetation is progressing.

API #: 083-06730

Inspection Photos
Location Name: CB 4
Location ID: 454998

11/15/24
359° N



Photo 3. View of eastern cut slope where vegetation is progressing.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 083-06730

Inspection Photos
Location Name: CB 4
Location ID: 454998

