

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403918968

Receive Date:

09/12/2024

Report taken by:

John Heil

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: PDC ENERGY INC	Operator No: 69175	Phone Numbers
Address: 1099 18TH STREET SUITE 1500		Phone: (303) 860-5800
City: DENVER	State: CO	Zip: 80202
Contact Person: Karen Olson	Email: taspillremediationcontractor@pdce.com	Mobile: ()

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 26030 Initial Form 27 Document #: 403220660

PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☒ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☒ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☐ Other: _____

SITE INFORMATION

Yes Multiple Facilities

Facility Type: WELL	Facility ID: _____	API #: 123-22408	County Name: WELD
Facility Name: DINNER 6-5-14	Latitude: 40.309538	Longitude: -104.738046	
** correct Lat/Long if needed: Latitude: 40.309536		Longitude: -104.738062	
QtrQtr: NESE	Sec: 14	Twp: 4N	Range: 66W Meridian: 6 Sensitive Area? Yes

Facility Type: SPILL OR RELEASE	Facility ID: 484087	API #: _____	County Name: WELD
Facility Name: Dinner 6-5-14 Separator FL Riser	Latitude: 40.304978	Longitude: -104.738474	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: SESE	Sec: 14	Twp: 4N	Range: 66W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications SM

Most Sensitive Adjacent Land Use Agricultural

Is domestic water well within 1/4 mile? Yes

Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

Nearest Well: Irrigation - 940' ESE; Surface Water: Irrigation Ditch - 335' E; Occupied Building: 905' E; Livestock: 893' E; FWS Wetlands: 696' WSW
Freshwater Emergent Wetland (PEM1Ax).

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- ☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste
- ☒ Produced Water ☐ Workover Fluids
- ☒ Oil ☐ Tank Bottoms
- ☒ Condensate ☐ Pigging Waste
- ☐ Drilling Fluids ☐ Rig Wash
- ☐ Drill Cuttings ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	Refer to Document No. 403530428	Confirmation Soil Sampling

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

On March 13 through 15, 2023, field screening and confirmation soil sampling activities were conducted in accordance with the ECMC Rule 911 during the decommissioning and closure of the Dinner 6-5-14 Wellhead and in-place abandonment of the associated flowline. Relevant figures can be found in previously submitted document no.403530428. Based on initial analytical results, it was determined that a historic release was discovered below the former separator flowline riser. Following the discovery, exploratory test pit soil borings (TP01-TP04) were advanced to depths ranging between 5 feet and 9 feet bgs. Due to the presence of remaining hydrocarbon impacts and active status of the tank battery, confirmation soil sampling activities were discontinued on March 15, 2023.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

- ☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

On March 13, 2023, one waste characterization soil sample (WC01) was collected from the separator source area at approximately 10 feet below ground surface (bgs) and submitted for laboratory analysis of the full ECMC Table 915-1 analytical suite. Analytical results indicated that site specific COCs include: benzene, toluene, ethylbenzene, and total xylenes (BTEX), naphthalene, total petroleum hydrocarbons (TPH[C6-C36]), 1,2,4-trimethylbenzene (TMB), 1,3,5-TMB, 1-methylnaphthalene (M), 2-M, arsenic, barium, and selenium. Soil analytical results, GPS coordinates and PID readings for the soil samples collected during confirmation sampling activities are included in Document No. 403530428. Soil sample locations, laboratory analytical reports and field notes & photo log are also included in the aforementioned document.

Proposed Groundwater Sampling

- ☒ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

If groundwater is encountered during supplemental site investigation or confirmation soil sampling activities, a grab sample will be collected as soon as practical. Groundwater samples will be submitted for laboratory analysis of BTEX, naphthalene, 1,2,4-trimethylbenzene, and 1,3,5-trimethylbenzene by EPA Method 8260.

Proposed Surface Water Sampling

- ☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

- ☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Soil encountered adjacent to wellhead infrastructure was visually inspected and field screened for VOC concentrations using a PID. Per the approved sampling plan, two wellhead soil samples were collected at depths of approximately 4 feet and 6 feet bgs from undisturbed areas most likely to be impacted by oil and gas operations located adjacent to and below production infrastructure. Soil samples WH01 and FLR01 were submitted for laboratory analysis of the ECMC Table 915-1 Organic Compounds in Soil, TPH (C6-C36), pH, EC, SAR, and boron. One soil sample was collected from along the flowline at the major change in direction (FL01-01) and was submitted for analysis of BTEXN, TMBs, and TPH (C6-C36). Analytical results indicated that organic compounds and soil suitability constituents were in compliance with the applicable ECMC Table 915-1 in all sample locations.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 4

Number of soil samples exceeding 915-1 1

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 100

NA / ND

-- Highest concentration of TPH (mg/kg) 5.4

-- Highest concentration of SAR 2.19

BTEX > 915-1 No

Vertical Extent > 915-1 (in feet) 10

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? Yes

Depth to groundwater (below ground surface, in feet)

Number of groundwater monitoring wells installed

Number of groundwater samples exceeding 915-1

Highest concentration of Benzene (µg/l)

Highest concentration of Toluene (µg/l)

Highest concentration of Ethylbenzene (µg/l)

Highest concentration of Xylene (µg/l)

Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION☐ Were impacts to adjacent property or offsite impacts identified?☐ Were background samples collected as part of this site investigation?☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☒ Is further site investigation required?

Based on the final analytical results, supplemental source mass removal activities will be conducted to remove remaining hydrocarbon impacted material via mechanical excavation in the vicinity of the failed soil samples WC01.

Up to five (5) background soil borings will be advanced in native material adjacent to the final excavation extent to assess ECOM Table 915-1 metal concentrations in native soil. Locations will be determined based on the final excavation event and will be advanced in areas not affected by oil and gas activities.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Remaining hydrocarbon impacted material will be removed via mechanical excavation and transported to an approved disposal facility under PDC waste manifests in accordance with Rules 905 and 906.

REMEDATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

During supplemental source mass removal activities, confirmation soil samples will be collected from the base and sidewalls of the final excavation extent. The soil samples will be submitted for laboratory analysis of the ECOM approved COC analyte suite. Supplemental source mass removal activities will be scheduled following approval of this form, facility shut-in, and landowner approval. Final analytical results will be summarized in a forthcoming Supplemental Form 27 within 90 days of completing the proposed scope of work or receipt of final analytical results.

Supporting documentation was included on the previously submitted Supplemental Form 27 Document No. 403530428.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

☐ Ex Situ

_____ Excavate and offsite disposal
_____ If Yes: Estimated Volume (Cubic Yards) _____
_____ Name of Licensed Disposal Facility or ECMC Facility ID # _____
_____ Excavate and onsite remediation
_____ Land Treatment
_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was not encountered during initial decommissioning activities at the Dinner 6-5-14 Wellhead or associated flowline.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

☒ Quarterly☐ Semi-Annually☐ Annually☐ Other

☐ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type:

☐ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☒ Other Third Quarter 2024 - Timeline Update

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Operator does not have site-specific financial assurance for this project; however, Operator has inactive well, blanket, and surface bonding including Surety IDs 106077122, 106473808, and 106473820, as well as commercial general liability and/or umbrella/excess insurance meeting the requirements of Rule 705.b. Operator does not anticipate making an insurance claim for this project.

- Further soil investigation/delineation is required

Costs included herein are estimates only and may change over time based on numerous factors. Accordingly, Operator makes no guarantees as to the accuracy of such cost estimates, thus providing an estimate for the next year below.

Operator anticipates the remaining cost for this project to be: \$ 15000

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

☐ Compliant with Rule 913.h.(1).

☐ Compliant with Rule 913.h.(2).

☐ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? _____

Does the previous reply indicate consideration of background concentrations? _____

Does Groundwater meet Table 915-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Following supplemental source mass removal activities at the former wellhead location, the location will be backfilled, compacted, and re-contoured to match pre-existing conditions. The location will be reclaimed in accordance with the ECMC 1000 series.

Is the described reclamation complete? Yes _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☒ Interim ☐ Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 03/15/2023

Proposed date of completion of Reclamation. 06/27/2028

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 08/08/2022

Actual Spill or Release date, or date of discovery. 03/14/2023

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 11/28/2022

Proposed site investigation commencement. 09/12/2024

Proposed completion of site investigation. 03/12/2025

REMEDIAL ACTION DATES

Proposed start date of Remediation. 03/15/2023

Proposed date of completion of Remediation. 06/27/2028

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☒ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

Proposed completion of site investigation date is being updated to reflect the schedule to complete the supplemental site investigation. The ECMC will be updated on a subsequent Form 27 with the results of the supplemental site investigation, or if the schedule is changed due to site access constraints.

OPERATOR COMMENT

This Supplemental Form 27 is being submitted as a Third Quarter 2024 timeline update for the Dinner 6-5-14 wellhead. Per ECMC request, tables and figures previously submitted have not been included with this form submittal. Please refer to ECMC document no. 403530428 for previously submitted tables and figures.

Following facility shut-in and landowner approval, supplemental source mass removal activities via mechanical excavation will be initiated to address the hydrocarbon impacts identified adjacent to the former Dinner 6-5-14 Separator. Supplemental Form 27s will be prepared and submitted on a quarterly schedule to provide updates and progress of the remediation until closure criteria has been achieved.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Karen Olson

Title: Remediation Advisor

Submit Date: 09/12/2024

Email: taspillremediationcontractor@pdce.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: John Heil

Date: 12/09/2024

Remediation Project Number: 26030

COA Type

Description

	ECMC has processed this form as an update; no analytical was attached thus approval of this form does not imply any agreement with comments on completion of site investigation. All ongoing/unaddressed comments/COAs from previous Forms remain applicable.
1 COA	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

403918968	INVESTIGATION/REMEDIATION WORKPLAN (SUPPLEMENTAL)
404020243	FORM 27-SUPPLEMENTAL-SUBMITTED

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)